

February 16, 2022

CE6000Plus-40/60/120 Cutting Plotters

Version 1.40

Release date: February 16, 2022

- Bug fixed
 1. When the message "USE THE POSITION KEY TO MOVE THE TOOL AND THEN PRESS ENTER" is displaying, the beeping will continue if the menu key will be pressed while the tool is moving.
 2. The plotter hung up when the PAUSE key was pressed while the second registration mark, or after, is searching.
 3. When the numeric part of the serial number starts with 0, the 0 was omitted if the first digit of the string obtained by the serial number acquisition command (ESC.C4;2;) is 0.

- Modification
 1. Added the command function to acquire the setting values in the plotter.

Version 1.30

Release date: June 6, 2018

- Modification
 2. The TOOL UP/DOWN RUNNING function was added to the Maintenance mode.
(This function is used in the production.)

Version 1.21

Release date: February 28, 2018

- Bug fixed
 1. The force of first line in the condition of current data was set to force of previous condition when the Panel mode was set to "ON".

Version 1.20

This version was not released.

- Bug fixed
 1. The cutting speed becomes slow when the straight line is cutting at the segment registration mark mode.
 2. Media dropped after segment registration mark of cutting job was finished

when the check box of advance after plot was checked in the CM4.

3. The error is displayed when the 20 mm reversed color of segment registration mark type 1 is detecting. It will stop before last one registration mark.
4. It cuts from incorrect position when the plot file was received after the origin was moved.

Version 1.10

Release date: June 7, 2017

- Modification
 1. Corresponded to the Auto feeder of ATS.

Version 1.00

Release date: January 26, 2017

- Initial version.

End