

*January 21, 2020*

---

## **CE7000 Series**

---

---

**Version 1.03**

**Release date: January 21, 2020**

---

- Fixed problem
  1. When data was receiving via the LAN port, it took about 10 sec to start cutting.
  2. The tool height did not reset after cutting was finished.
  3. The spelling miss in the error code E05017 was corrected.
  4. The spelling miss in the error code E04018 was corrected.
  5. The refresh value for the SDRAM was incorrect.
  6. When the serial number was started from "0", the first digit of "0" could not display at the serial number menu in the maintenance mode.
  
- Modification
  1. The aging was process was change for production.

---

**Version 1.02**

**Release date: September 18, 2019**

---

- Fixed problem
  1. The extra blade angle correction was performed for the initial blade angle correction when there is large angle from the X axis.
- Modification
  1. The confirmation procedure was changed for the cutting area in the production line.

CE7000-130/160:  
When the A4 size of sheet was loaded, confirm it will plot the 247 mm for vertical direction.

CE7000-40/60:  
When the A4 size of sheet was loaded, confirm it will plot the 252 mm for vertical direction.
  2. The aging time was reduced.

---

**Version 1.00**

**Release date: June 20, 2019**

---

- Initial version

End