
i-Mark Plus 1.0 software

Version 9.4.0

Release date: May 28, 2021

- Bug fixed
 1. Sometimes the system stopped during continuous sheet feed.
 2. The system sometimes stop at a specific number of sheets when sending data with a short cutting time on continuous operation
 3. While the software was running, the system stopped only the first time after the USB hub/cable reconnected.

Version 9.2.1

Release date: November 13, 2020

- Modification
 1. When the command setting of CE7000-40 was set to “AUTO”, the i-Mark Plus 1.0 did not detect the Cutting width correctly.
 2. The i-Mark Plus 1.0 corresponded to the CE6000-ASF.

Version 9.1.4H

Release date: October 1, 2019

- Initial version